

Wireline Entry Guide with Pump-Out Plug

The Performance Oil Tools, Inc. Wireline Entry Guide with Pump-Out Plug provides a means of temporarily plugging the bottom of a tubing string to avoid fluid flow up the tubing while tripping in the hole. The Pump-Out Plug is removed by filling the tubing with fluid and applying a pressure above the plug sufficiently greater than the normal well pressure at the tool to shear the retaining shear screws and pump the plug out of the Wireline Entry Guide. The plug will then fall to the bottom of the well.

Specification Guide Pump-Out Plug

Thread	Guide ID*	Guide OD
2-3/8 EU Box	2.000"	3.063"
2-7/8 EU Box	2.441"	3.687"
3-1/2 EU Box	3.000"	4.500"

*ID after pump-out

